


NOV 24 2003

Photo No. 1 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - concrete pump island



NOV 24 2003

Photo No. 2 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - concrete pump island



Photo No. 3 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - storm drain in parking area behind maintenance building




Photo No. 4 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - wet pavement area from service bay doors towards the storm drain in the parking area




Photo No. 5 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - wet pavement area from service bay doors towards the storm drain in the parking area



Photo No. 6 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - wet pavement area from service bay doors towards the storm drain in the parking area



Photo No. 7 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - vehicle wash bay, wet pavement outside of bay door






Photo No. 8 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - inside of service bay #1 looking out towards storm drain in parking area






Photo No. 9 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Gerard Crutchley - floor drain in maintenance building behind service bays #1 & #2



Photo No. 10 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - oil/water separator unit in maintenance building floor





Photo No. 11 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Gerard Crutchley - metal cover in oil/water separator unit in maintenance building floor

floor drain



floor drain

Photo No. 12 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - floor drains in shop floor




Photo No. 13 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - exhaust air filters in paint spray booth



Photo No. 14 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - paint spray gun washing unit




Photo No. 15 - USPS, Baltimore, Vehicle Maintenance, 11/24/03, Jose Jimenez - evaporator unit for recovering solvent from paint spray gun washing unit